





5

Stabilising anchors retracted



6

Stabilising anchors deployed



5 a x2





6 a x2



5 b



4





6 b




4


6 a




7 a




7 b




7 d



7 c




7 e




7 f



7 h



7 i






7 g




7 j








9 e





9 f



9 g



9 h





10




PULSE DRIVER CANNON

11




PULSE BLASTCANNON


10 a





10 b x3




10 c





10 e



10 d






10 f




COOLING VENTS OPENED






11 a




11 b



11 c




12






13 a



13 b



13 c



13 d




21



13 c

13 e



10 / 11

13 b



13 d



10 / 11



10



10



11

